

# Rental Conditions EMEA

## **Please Note!**

The framework conditions listed in this supplement are used to further explain the procedure for renting Kaye measurement equipment and are part of the rental agreement. By signing, the customer agrees to these conditions. Irrespective of the explanations given in the rental conditions, our General Terms and Conditions apply: <a href="https://www.kayeinstruments.com/en/about-us/terms-conditions">https://www.kayeinstruments.com/en/about-us/terms-conditions</a>.

If you have further questions, please contact our service department or one of our sales representatives.

#### Important!

Amphenol Advanced Sensors Germany GmbH requires these rental conditions to be signed, together with a written order, before delivery of the rental systems as part of the rental agreement.

## 1. RENTAL PERIOD

#### • EU Countries:

- Minimum rental period: 1 week
- o Minimum rental period for calibration baths: 4 weeks

## • Non-EU Countries:

- Minimum rental period: 2 weeks
- Minimum rental period for calibration baths: 4 weeks

# 2. RENTAL ORDER

- For a rental order to be carried out/executed, the following documents are required BEFORE delivery
  - Written rental order / order
  - Signed form: rental conditions

Without these documents we cannot guarantee timely delivery.

## 3. RENTAL RATES AND PRICING

See attached quote or rental information sheet.

## Note:

- Each calendar week that has begun will be invoiced
- The first invoice will be sent immediately after shipment in the respective calendar month. Additional rental weeks will be charged in the respective calendar month.

#### 4. SHIPPING, HANDLING AND INSTALLATION

- The delivery address for the rental equipment will be taken from the order. Please ensure that it is correct. Non-usable rental periods due to incorrect delivery information will still be charged.
- The customer is responsible for shipping charges to and from their facilities. The return shipment is also the responsibility of the customer.
- Shipping/transport times to the customer are not included in the rental period. The rental period ends as soon as the rental system is returned to our Pforzheim, Germany incoming goods department. Shipping/transport times of the return are thus part of the rental period.



- Amphenol Advanced Sensors Germany GmbH always ship FCA via UPS or DACHSER. It is highly recommended to return the equipment the same way.
- Other delivery services can be used but must be explicitly stated in the order, including the customer's account number with the freight service company.
- Amphenol Advanced Sensors is not responsible for the installation or commissioning of the rental systems.
- Amphenol advanced Sensors reserves the right, in exceptional cases, to reclaim the rented rental systems from the customer with immediate effect after expiry of the originally stated rental period.
- Minimum Computer Specifications: When using a computer NOT provided by Amphenol Advanced Sensors, it is essential to clarify the necessary IT requirements BEFORE placing the rental order. In general, Windows 7™ and an unused USB port are required for Kaye Validator 2000 and Kaye ValProbe systems. Kaye Validator AVS systems and ValProbe RT are shipped with a console/tablet PC (software pre-installed).

## **Important Note:**

All rental systems are checked for functionality and completeness by Amphenol Advanced Sensors before delivery.

Irrespective of the initial inspection carried out by Amphenol Advanced Sensors, the rental system must also be checked for completeness and full functionality **immediately upon receipt** by the customer.

Problems during commissioning or missing accessories which do not allow the use of the rental system must be reported to Amphenol Advanced Sensors in writing within 5 working days of receipt. In the event of non-compliance with the complaint period, no consideration will be given to the calculation of the total rental period.

## 5. RETURN OF EQUIPMENT

Return only to:

Amphenol Advanced Sensors Germany GmbH - Rental Department - Sinsheimer Straße 6 75179 Pforzheim Germany

Return in original packaging only.

# 6. INSURANCE / LIABILITY/ DAMAGE:

- The rental equipment remains the property of Amphenol Advanced Sensors. The customer may not sub-let the rental equipment without the written permission of Amphenol Advanced Sensors or issue it for use to third parties or to resell it. The place of use of the rental equipment is the delivery address stated to Amphenol Advanced Sensors. The customer is liable to Amphenol Advanced Sensors for all damages and disadvantages caused to Amphenol Advanced Sensors by the breach of this provision.
- Amphenol Advanced Sensors grants the customer a non-transferable right of use for the hired property valid during the rental period. Amphenol Advanced Sensors and customer agree that all rights to the rented property, including any copies, remain with Amphenol Advanced Sensors. The customer must ensure that operating instructions, software and associated documentation are not



made accessible to third parties. Copies of the software may not be made. All license conditions have to be met. In case of non-conformance, the customer is fully liable.

- Rental equipment is dispatched according to INCOTERM 2010 FCA Pforzheim / Germany and is uninsured.
- Loss in return transport of the rental equipment will be charged to the customer.
- The customer is responsible for the intended use of the rental system, its proper storage and its secure return in original packaging.

Upon receipt of returned rental systems, Amphenol Advanced Sensors will inspect the equipment. Damage caused by transport, improper handling, missing accessories (e.g., cables, manuals, software CDs), defective electronic components, and damage due to misuse, as well as signs of excessive wear and tear, are the responsibility of the customer.

Start of Rental Period (Date)	Estimated length of Rental Period (Date)
Kaye Validator2000 / AVS / Console/ ValProbe / ValProbe RT / Laptop	Kaye IRTD / Temp. Reference
Please state software/firmware version needed! Especially when ordering VRT logger.	Email
Email to which the As-Found calibration report should be send to, after return to Amphenol Advanced Sensors	Email
	Date
Stamp / Company Name	
Title / Name	Signature

Contact:

Amphenol Advanced Sensors Germany GmbH Sinsheimer Straße 6 75179 Pforzheim Germany Tel. Rental Department: +49 (0)7231 14335-43

Tel.: +49 (0)7231 14335 0 Fax: +49 (0)7231 14335 29

Email: <u>Kaye-CCPF@amphenol-sensors.com</u>

<sup>01.</sup> January 2024 – Conditions of Sales: All prices are NET FCA, Pforzheim and INCOTERMS 2020. Subject to change

<sup>© 2024</sup> Amphenol Corporation. All Rights Reserved. Specifications are subject to change without notice.

Other company names and product names used in this document are the registered trademarks of their respective owners.